

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EO718
East
> 1
1.012 mi.
5344 ft.

MANHOLE 36471
NEPTUNE AV / CONEY ISLAND
BROOKLYN, NY

NY Spills S105235544
N/A

Site 5 of 8 in cluster EO

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: MANHOLE 36471
Address: NEPTUNE AV / CONEY ISLAND
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0107368 / 2004-09-10
Facility ID: 0107368
Facility Type: ER
DER Facility ID: 104890
Site ID: 120832
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2001-10-17
Investigator: AERODRIG
Referred To: Not reported
Reported to Dept: 2001-10-17
CID: 365
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False

Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-10-17
Spill Record Last Update: 2004-09-10
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ E2MIS notes: While getting ready to work on sch fdr 7b54 in MH36471 he found approximately 1 oz of unknown oil on 1500 gallons of water. He does not see a sump or sewer connection at this time. Took a liquid sample for PCB. 10/17/2001: Sample results came as 736 ppm. Tanker ordered. Crew assembled to do cleanup. UPDATE OCT 17 2001 2220HRS . J DEKANCHUK ENVIROMENTAL O/S REPORTS WATER FROM MH IS PUMPED INTO TANKER. MANHOLE IS DOUBLE WASHED FROM TOP. MH MAKES WATER. CLEANUP AND MEET WITH FOD TO RESUME AT 10/18/01 IN THE AM. UPDATE @1950HRS 11/08 J.DEKANCHUK REPORTS OIL & WATER REMOVED BY TANKER, 3 BARRELS OF HAZARDOUS SOLID WASTE REMOVED. DOUBLE WASHED AND SDDA BLASTED STRUCTURE, WASTE WATER REMOVED BY TANKER, 21 WIPE SAMPLES TAKEN BY CHEMIST. TAG REMAINS IN PLACE PENDING RESULTS. 11/12/01---O.S.DEKANCHUK REPORTS ALL WIPE SAMPLES RETURNED UNDER 10 UG/100CM2."
Remarks: "1 OZ UNK OIL ON 1500 GALLONS OF WATER - CLEAN UP PENDING LAB RESULTS - REF #139818"

All Materials:
Site ID:

120832

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 845564
Operable Unit: 01
Material ID: 532187
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported